



# Liquid Touch Graphics

## Application Instructions


\*All parts should always be clean and free of grease and dirt before applying

Items needed - Deionized water, container for water, spray bottle, squeegee, lint free towel or rag.




- 1** Place product into water container. Make sure the entire product is submerged and not curled, allowing the part to be completely saturated.


- 2** Soak for a minimum of 60 seconds




- 3** Apply water in a mist with spray bottle to the area where the graphic will be applied



- 4** Remove from water and check the graphic at the corner for release from the backing paper.




- 5** Separate one end of graphic from the paper and roll back under the graphic. Continue to pull paper in a flat position back against the graphic.




**6** Slide the graphic into position before you start to squeegee.

**7** Use a wet cloth to smooth out any large air bubbles.




**8** Use squeegee to remove any remaining bubbles or water.

**9** Use a rag or towel to dry top surface and remove excess water from surrounding surfaces.



**10** Go back using squeegee to remove any small bubbles or any additional water pockets that were missed from under the graphic.



**11** Dehydrate - See procedure

*Speed Graphics*