



Liquid Touch Graphics

Application Instructions


*All parts should always be clean and free of grease and dirt before applying

Items needed - Deionized water, container for water, spray bottle, squeegee, lint free towel or rag.




- 1** Place product into water container. Make sure the entire product is submerged and not curled, allowing the part to be completely saturated.


- 2** Soak for a minimum of 60 seconds




- 3** Apply water in a mist with spray bottle to the area where the graphic will be applied



- 4** Remove from water and check the graphic at the corner for release from the backing paper.




- 5** Separate one end of graphic from the paper and roll back under the graphic. Continue to pull paper in a flat position back against the graphic.




6 Slide the graphic into position before you start to squeegee.

7 Use a wet cloth to smooth out any large air bubbles.



8 Use squeegee to remove any remaining bubbles or water.

9 Use a rag or towel to dry top surface and remove excess water from surrounding surfaces.



10 Go back using squeegee to remove any small bubbles or any additional water pockets that were missed from under the graphic.



11 Dehydrate - See procedure

Speed Graphics